§27.805 Flight crew emergency exits.

- (a) For rotorcraft with passenger emergency exits that are not convenient to the flight crew, there must be flight crew emergency exits, on both sides of the rotorcraft or as a top hatch in the flight crew area.
- (b) Each flight crew emergency exit must be of sufficient size and must be located so as to allow rapid evacuation of the flight crew. This must be shown by test.
- (c) Each flight crew emergency exit must not be obstructed by water or flotation devices after an emergency landing on water. This must be shown by test, demonstration, or analysis.

[Doc. No. 29247, 64 FR 45094, Aug. 18, 1999]

§27.807 Emergency exits.

- (a) Number and location. (1) There must be at least one emergency exit on each side of the cabin readily accessible to each passenger. One of these exits must be usable in any probable attitude that may result from a crash;
- (2) Doors intended for normal use may also serve as emergency exits, provided that they meet the requirements of this section; and
- (3) If emergency flotation devices are installed, there must be an emergency exit accessible to each passenger on each side of the cabin that is shown by test, demonstration, or analysis to;
 - (i) Be above the waterline; and
- (ii) Open without interference from flotation devices, whether stowed or deployed.
- (b) Type and operation. Each emergency exit prescribed by paragraph (a) of this section must—
- (1) Consist of a movable window or panel, or additional external door, providing an unobstructed opening that will admit a 19-by 26-inch ellipse;
- (2) Have simple and obvious methods of opening, from the inside and from the outside, which do not require exceptional effort;
- (3) Be arranged and marked so as to be readily located and opened even in darkness; and
- (4) Be reasonably protected from jamming by fuselage deformation.
- (c) *Tests*. The proper functioning of each emergency exit must be shown by test.

(d) Ditching emergency exits for passengers. If certification with ditching provisions is requested, the markings required by paragraph (b)(3) of this section must be designed to remain visible if the rotorcraft is capsized and the cabin is submerged.

[Doc. No. 29247, 64 FR 45094, Aug. 18, 1999]

§27.831 Ventilation.

- (a) The ventilating system for the pilot and passenger compartments must be designed to prevent the presence of excessive quantities of fuel fumes and carbon monoxide.
- (b) The concentration of carbon monoxide may not exceed one part in 20,000 parts of air during forward flight or hovering in still air. If the concentration exceeds this value under other conditions, there must be suitable operating restrictions.

§ 27.833 Heaters.

Each combustion heater must be approved.

[Amdt. 27-23, 53 FR 34210, Sept. 2, 1988]

FIRE PROTECTION

$\S\,27.853$ Compartment interiors.

For each compartment to be used by the crew or passengers—

- (a) The materials must be at least flame-resistant:
 - (b) [Reserved]
- (c) If smoking is to be prohibited, there must be a placard so stating, and if smoking is to be allowed—
- (1) There must be an adequate number of self-contained, removable ashtrays; and
- (2) Where the crew compartment is separated from the passenger compartment, there must be at least one illuminated sign (using either letters or symbols) notifying all passengers when smoking is prohibited. Signs which notify when smoking is prohibited must—
- (i) When illuminated, be legible to each passenger seated in the passenger cabin under all probable lighting conditions; and
- (ii) Be so constructed that the crew can turn the illumination on and off.

[Amdt. 27–17, 45 FR 7755, Feb. 4, 1980, as amended by Amdt. 27–37, 64 FR 45095, Aug. 18, 1999]